

## UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

**REGION VI** 1445 ROSS AVENUE, SUITE 1200 DALLAS, TEXAS 75202

## **MEMORANDUM**

DATE:

October 25, 1988

SUBJECT: Potential Hazardous Waste Site - Site Inspection Report

FROM:

Oscar Cabra, Jr., P.E

Chief

Water Supply Branch (6W-S)

T0:

Presley Hatcher

Acting Chief

Superfund Compliance Section (6H-ES)

In response to the CERCLA investigation reports which you recently sent to the Water Supply Branch, I am attaching our comments. Thank you for the opportunity to review these documents.

Attachments: Air Center

Oklahoma City, Oklahoma

OKD98075031

cc: Carl Hickam (6H-ES)

9831270 

## REVIEW

## Potential Hazardous Waste Site - Inspection Report

Site Name Un Conter
Site Location OK City, OK
Site Number STFAFB29 30KD980750315
Date of Survey 8/23/88 Sample Collection
Inspected by State FIT TAT
Other (specify)
Received From Dave Wineman (6E-SH)
Date rec'd by Water Supply Branch 10/6/88
Type samples:
on-site on-site on-site on-site  SOIL SURFACE WATER X GROUND WATER DRINKING WATER  off-site off-site off-site
Type contaminant(s):
ORGANICS X INORGANICS RADIONUCLIDES MICROBIOLOGICAL
Summary:
The confirmation samples for lead analysis. #23, \$ from the eity of Bethamy's municipal wells have been collected and analysis as requested by Water Supply Branch . All results are below the national primary durphing water regulation Standard of 50 ug/l.
Furthernore, as noted in the ROC dated 8-1-88 to
Prishy Hatcher (6H·ES), The Oblahoma State Department (050H) in Health was requested a capy of these sets of Sample results. The water Supply Branch will submit these results to 050H.

Concurrence:

Edgar 4. Jeffing for T. L. 10/21/88